

Carb vent tube from 2012 EVO went up inside right hand side panel -that petrol cap vent is available to stop direct ingress of water.



On later years, the carb vent tube goes up inside the frame so that it is protected from direct ingress

